

Photo Attachments



Poor drainage/low lying area at the corner of this garage.



Ice showing the path of the drainage and point of entry under the driveway.



This driveway has heaved 1/2 an inch this winter due to poor drainage.